

**To:** hammondbh@cdmsmith.com[hammondbh@cdmsmith.com]; Hoppe, Michael[Hoppe.Michael@epa.gov]  
**Cc:** John Rolfe[jrolfe@demaximis.com]  
**From:** Stan Kaczmarek  
**Sent:** Thur 4/3/2014 3:15:55 PM  
**Subject:** Re: 10.9

Been told it is not looking good for fabric placement today. Still need to see. The new shroud was delivered yesterday but I do not believe it is hooked up. John Rolfe is on site today and he can update all of us as the day progresses.

>>> &quot;Hoppe, Michael&quot; <Hoppe.Michael@epa.gov> 04/03/14 10:37 AM >>>  
Flow at dam looks like it is still up (4700+ cfs). Any chance at panel placement today? Also did the upgraded assembly come in for the poseidon barge?

Michael Hoppe  
Federal On-Scene Coordinator  
USEPA Region 2  
Response and Prevention Branch  
Preparedness Section  
Phone: (732) 906-6908 Fax: (732) 321-4425  
Cell: (908) 420-4472

[ER logo (R2 modified CAPs lsmall)]